





COMMUNITY PARK SUBSTATION

Project Location:

Casper, Wyoming

Project Description:

The project consisted of geotechnical investigation for substation expansion. The geotechnical analysis consisted of shallow and deep foundation analysis for proposed substation structures. The sampling involved the use of different drilling techniques due to difficult drilling conditions encountered. The subsurface conditions encountered swelling soils and hard clayey (shale) soils.